


## Recommended Cutting Conditions

### ■ Shoulder Milling

(inch)


Workpiece Material		Carbon Steels, Alloy Steels, Mild Steels				Titanium Alloys, Austenitic Stainless Steels, Ferritic and Martensitic Stainless Steels				Precipitation Hardening Stainless Steels			
		AISI 1045, AISI 4140				Ti-6Al-4V, AISI 304, AISI 316LN, AISI 410, AISI 420J2				AISI 630, AISI 631			
DC		Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>	Width of Cut <b>ae</b>	Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>	Width of Cut <b>ae</b>	Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>	Width of Cut <b>ae</b>
<b>10</b>	<b>.3937</b>	4800	33.9	.315	.157	2000	12.6	.315	.157	1900	9.1	.315	.157
<b>12</b>	<b>.4724</b>	4000	31.5	.378	.189	1900	13.4	.378	.189	1600	9.1	.378	.189
<b>16</b>	<b>.6299</b>	3000	23.6	.504	.252	1400	11.0	.504	.252	1200	7.9	.504	.252
<b>20</b>	<b>.7874</b>	2400	20.9	.630	.315	1100	8.7	.630	.315	950	7.1	.630	.315
Depth of Cut													



### ■ Slot Milling

(inch)

Workpiece Material		Carbon Steels, Alloy Steels, Mild Steels			Titanium Alloys, Austenitic Stainless Steels, Ferritic and Martensitic Stainless Steels			Precipitation Hardening Stainless Steels		
		AISI 1045, AISI 4140			Ti-6Al-4V, AISI 304, AISI 316LN, AISI 410, AISI 420J2			AISI 630, AISI 631		
DC		Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>	Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>	Revolution <b>n</b> (min <sup>-1</sup> )	Feed Rate <b>vf</b> (IPM)	Depth of Cut <b>ap</b>
<b>10</b>	<b>.3937</b>	3200	20.1	.197	1900	9.1	.197	1300	3.9	.197
<b>12</b>	<b>.4724</b>	2700	19.3	.236	1600	10.2	.236	1100	4.3	.236
<b>16</b>	<b>.6299</b>	2000	15.7	.315	1200	8.7	.315	800	3.8	.315
<b>20</b>	<b>.7874</b>	1600	13.8	.394	950	6.7	.394	640	3.5	.394
Depth of Cut										



DC = Dia.

Note 1) Vibration may occur if the rigidity of machine or workpiece is low. In this case, please reduce the revolution and feed rate proportionately, or set a lower depth of cut.

Note 2) If the depth of cut is shallow, the revolution and feed rate can be increased.

Note 3) For stainless steel, titanium alloy, the use of water-soluble coolant is effective.