RECOMMENDED CUTTING CONDITIONS

Steel Shank						I/d ≤ 3		3 < I/d ≤ 5	
Heavy Metal Shank						I/d ≤ 3		3 < I/d ≤ 6	
Work Material	Cutting Mode	Breaker	Recom- mendation	Grade	Cutting Speed (SFM)	Feed (IPR)	D.O.C. (inch)	Feed (IPR)	D.O.C. (inch)
Mild Steel <180HB	Finishing	FV	1	NX2525	555 (390-720)	.004 (.002006)	020	.004 (.002006)	020
	Light	sv	1	VP45N	460 (295—620)	.008 (.004—.010)	040	.006 (.002—.008)	040
			2	VP15TF	590 (425—755)	.008 (.004—.010)	040	.006 (.002—.008)	040
	Medium	MV	1	VP45N	425 (260-590)	.010 (.006—.014)	080	.008 (.006—.010)	060
			2	VP15TF	525 (360-690)	.010 (.006—.014)	080	.008 (.006—.010)	060
Carbon Steel Alloy Steel 180—280HB	Finishing	FV	0	VP15TF	460 (295—620)	.004 (.002—.006)	020	.004 (.002—.006)	020
			2	NX2525	425 (260—590)	.004 (.002—.006)	020	.004 (.002—.006)	020
	Light	sv	1	VP15TF	425 (260—590)	.008 (.004—.010)	040	.006 (.002—.008)	040
			2	UE6020	460 (295—620)	.008 (.004—.010)	040	.006 (.002—.008)	040
	Medium	MV	1	VP15TF	390 (230—555)	.010 (.006—.014)	080	.008 (.006—.010)	060
			2	UE6020	425 (260-590)	.010 (.006—.014)	080	.008 (.006—.010)	060
Stainless Steel 180—280HB	Finishing	FV	1	VP15TF	490 (360—620)	.004 (.002—.006)	020	.004 (.002—.006)	020
	Light	sv	1	US7020	490 (360-620)	.008 (.004—.010)	040	.006 (.002—.008)	040
			2	VP15TF	425 (295—555)	.008 (.004—.010)	040	.006 (.002—.008)	040
	Medium	MV	1	US7020	460 (330—590)	.008 (.006—.010)	080	.008 (.006—.010)	040
			2	VP15TF	390 (260-525)	.008 (.006—.010)	080	.008 (.006—.010)	040
Cast Iron Tensile Strength<350MPa	Finishing	F/FS	1	HTi10	425 (295—525)	.006 (.004—.008)	020	.006 (.004—.008)	020
	Medium	MV	1	VP15TF	295 (195—390)	.008 (.006—.010)	080	.008 (.006—.010)	060
N Aluminium Alloy	Finishing	F/FS	0	HTi10	985 (655—1310)	.004 (.002—.006)	020	.004 (.002—.006)	020
		No Breaker	1	MD220	655 (490—820)	.004 (.002—.006)	080	.004 (.002—.006)	040
H Heat Treated Steel 35-65HRC	Finishing	No Breaker	1	MB825	330 (260-655)	.004 (.002—.006)	006	.004 (.002—.006)	004

^{*} If the DIMPLE BAR vibrates, reduce cutting speed to 70% of the above.